


- 1.Hose : The three hoses are used individually for fuel gas, preheating oxygen and cutting oxygen.
2. Cross hand wheel : To adjust the horizontal distance of torch
3. Cross gear rack
4. Vertical adjusting hand wheel of torch
5. Tip
- 6.Thermal baffle : To prevent the heat diffusing into the inner of machine.
7. Fuel gas two-port valve : To adjust gas-flow rate.
8. Gas distributor.
9. Clutch hand knob: "STOP" is parting, "START" is combination.
10. Body
11. Speed controller : Increase the speed from "0"to"10"Decrease speed from "10" to "0".
12. Outlet
13. Universal wheel

Specifications	
MODEL	CG1-30
Input Voltage (V)	AC480 ± 10%
Speed Control	Silicon
Cutting Speed (mm/min)	50-750
Cutting Thickness (mm/min)	50-100
Groove Angle (°)	0-45
Diameter of cutting circle (mm)	20-2000
Tip	G02 (Acetylene), G03 (Propane)
Dimension (mm)	435 x 210 x 240
Machine Weight (Kg)	16
Accessories Weight (Kg)	7.8

Come with accessories

1.8m Metal Rail



Singapore HQ
Blk 6 Marsiling Industrial Estate Road 1
#01-14 Singapore 739275

Showroom
No. 3 Soon Lee Street, Pioneer
Junction #01-37 Singapore 627606

Myanmar
No. 760A, Pyi Htaung Su, Main Road
65 Quarters, Industrial Zone (2) South Dagon
Yangon, Myanmar

www.danoxwelding.com
sales@danoxwelding.com

Indonesia- Pt. Inti Bangunan Perkasa
No. 15-17 Jalan Pelita 1, Batam, Kepulauan Riau
29453

Retail
Blok D, No. 5 Jalan Pembangunan 2, Komplek
Batama, Batam, Kepulauan Riau- 29432